

Mike Kehoe
Governor

Mark S. James
Director, Public Safety

J. Tim Bean
State Fire Marshal



205 Jefferson Street, Suite 1315
Mailing Address: P.O. Box 844
Jefferson City, MO 65102
Telephone: (573) 526-3660
Fax: (573) 526-5971
Email: elevator@dfs.dps.mo.gov

Missouri Department of Public Safety Division of Fire Safety

April 07, 2025

Rita Dillard
Regional Arts Center
6128 Delmar Blvd
St. Louis, MO 63112

Rita Dillard
Regional Arts Center
6128 Delmar Blvd
St. Louis, MO 63112

Operating Certificate Overdue

A valid Operating Certificate is overdue for the equipment listed below at the location shown.

The reason(s) a valid Operating Certificate overdue is indicated in the **Due**, **Viol**, and **Fee** columns as follows:

- **Due** – The required annual or other inspection(s) have not been received. Please contact your elevator service company and a state-licensed inspector to schedule and complete any required inspection(s) as soon as possible.
- **Viol** – Notification that ALL reported violations have been corrected has not been received. Please return a signed and dated Inspections - Violations letter certifying all violations has been corrected as soon as possible.
- **Fee** – The fees due to obtain an Operating Certificate have not been received. Please pay the invoice for inspection and Operating Certificate fees as soon as possible.

Please contact your elevator service company and/or a state-licensed inspector to schedule and complete any required inspection(s) or assistance to resolve violations.

Failure to obtain a valid Operating Certificate may result in the shutdown of your equipment and/or assessment of fines.

You may make an online payment by following the instructions at this URL: <https://mo-dfs-equipinspect.azurewebsites.net/Payment>

If you need further assistance, please contact our office at (573)526-3660.

Location: Regional Arts Center - 6128 Delmar Blvd, St. Louis, MO 63112

Equip. ID	Serial No.	Type	Location in Bldg.	Inspection Due Date	Due	Viol	Fee
14057	18750318	Passenger Hydraulic	#1	07/14/2025		✓	✓
14057	18750318	Passenger Hydraulic	#1	07/14/2025		✓	✓

Regards,

A handwritten signature in black ink, appearing to read "Gus Guadalupe".

Gus Guadalupe
Deputy Chief Elevator Inspector